MARYLAND HISTORICAL TRUST WORKSHEET

NOMINATION FORM for the

NATIONAL REGISTER OF HISTORIC PLACES, NATIONAL PARKS SERVICE

). NAME									
	COMMON:					, 1990 . - 1991.			
	AND/OR HISTORIC:	. • •				The state of the s			
	Pennyfield	Lock Hous	e, Lock, a	nd Stor	re Building	The continue Salangines against			
2.	LOCATION			-	-				
	STREET AND NUMBER		-1			The second se			
	End of Pennyfield Lock Road								
	Potomac				•				
	STATE	er en	COI	YTY:					
2200000000	Maryland Montgomery Montgomery								
3	CLASSIFICATION			•	ı .				
are .	CATEGORY (Check One)		OWNERSHIP	STATUS ACCESSIBL					
	District Building	Public	Public Acquisition:		Occupied	Yes: Distance			
	Site Structure] Private	☐ In Process		Unaccupied	Restricted			
	☐ Object] Both	Being Cons	sidered	Preservation work	Unrestricted			
					in pragress	₩ No			
٠٠,	PRESENT USE (Check One or More	e as Appropriate)	•						
·	Agricultural Gove	-	Park		Transportation	☐ Camments			
-	Commercial Indus	-	Private Residence		Other (Specify)	A CONTRACTOR			
	☐ Educational ☐ Milite ☐ Entertainment ☐ Muse	,	Religious						
		om	Scientific						
	OWNER OF PROPERTY OWNER'S NAME:								
	National Pa	rk Service	e IIS Der	nartmor	at of the T	ntorior			
	STREET AND NUMBER:	TH DOLVIO	c, c.b. be	Jan Giler	ic or the r	ncerior			
	CITY OR TOWN:	w		STATE:					
	Washington,	DC		31212:		•			
5. 1	OCATION OF LEGAL DESCRI	PTION				1944			
	COURTHOUSE, REGISTRY OF DEE					362			
	Montgomery (County Co	urthouse						
	STREET AND NUMBER:								
	CITY OR TOWN:			STATE					
	Rockville				/land				
	Title Reference of	Current	Deed (Book	& Par	#):				
6: REPRESENTATION IN EXISTING SURVEYS									
TITLE OF SURVEY:									
Historic American Buildings Survey									
	DATE OF SURVEY: 1936 DEPOSITORY FOR SURVEY RECO	ROS:	Federal	State	County	Local			
	Library of (Congress							
STREET AND NUMBER:									
10 First Street SE									
	Washington, DC								

		•		
		ľ	1	
		ľ	1	
		_		•
		2		
		L	•	,
		-		
		7		
		C		
•		(
		-		
	,		•	

and the second s						
•	* + + +		, All Control of the	1:25-15		
7. DESCRIPTI	ON					
CONDITIO	N Excellent	Good	(Check	iarated 🔲 Ruin		7 . 1 .
	M Alte	• •	Incitered) Maved	Check One) Original Si	te ::
DESCRIBE T	HE PRESENT A 10 OF	RIGINAL (If known) P	HYSICAL APPEAR			
To To	ne lock hous	se is a sto	me buildir	og with a t	hree hav	
	ic room nous	30 15 a 500	De Maria		All all and a light	
faca	de. The cer	ntral bay i	s the door	way; flank	ing window	s :
are	6/6 double h	nung sash.	The linte	ls over do	or and	1
wind	ows are heav	vy beams.	The flush-	gable end	chimneys	
have	brick stack	ks.				
T)	he store is	a frame bu	ilding wit	h the gabl	ed facade	
faci	ng the cana:	l. It has	a porch ex	tending ar	ound	
seve	ral sides of	f the build	ling. It i	s now used	l as a hous	e.
	•					v (* 157
			;	Ž.		
	,			4		
				*		
		·	•			
			į		· · · · · · · · · · · · · · · · · · ·	

PERIOD (Check One or More ee	16th Century	☐ 18th Century	20th Century
15th Century	☐ 17th Century	19th Century	
SPECIFIC DATE(S) (If Applicable	le end Known)		
AREAS OF SIGNIFICANCE (Che	ck One or More ee Appropri	ate)	—
Abar iginal	☐ Education	Politicol	Urbon Planning
☐ Prehistoric	Engineering	Religion/Phi-	Other (Specity)
Historic	☐ Industry	losophy	
Agriculture	☐ Invention	Science	
Architecture	☐ Landscape	☐ Sculpture	
☐ Art	Architecture	Social/Humon-	
Commerce	Literature	itorion	
Communications	☐ Militory	☐ Theater	
Conservation	☐ Music	☐ Transportation	
STATEMENT OF SIGNIFICANCE			4 7 4
		- 'b '-	
			,
			•



2	MAJOR	BIBLIOGRAPHICAL RE	FERENCES -			Activities of the contract of				
1						The second secon				
		. •	*							
			en de la companya de		ر الموادية الموادية الموادية الموادية ال					
					entre de la companya del companya de la companya del companya de la companya de l	erikan di kaban di k Kaban di kaban di kab				
			The second of th		ger in the state of the state o	in the second reality				
			पर्व स्थिति । तस्य में सूच्या करिया । हिंदी स्थापन		my manager					
			en e e e e e e e e e e e e e e e e e e		The state of the s	and the second				
		e e e e e e e e e e e e e e e e e e e	100 miles (100 miles)							
10	GEOGI	PAPHICAL DATA								
20000	10. GEOGRAPHICAL DATA LATITUDE AND LONGITUDE COORDINATES									
	OEFIN	OEFINING A RECTANGLE LOCATING THE PROPERTY			DEFINING THE CENTER POINT OF A PROPERTY					
	GORNER	LATITUOE	LONGITUOE		LATITUOE	LONGITUOE				
	NW	Degrees Minutes Seconds	Degrees Minutes Seconds		Degrees Minutes Seconds	Degrees Minutes Seconds				
	NE	• • •								
4.	\$E		*							
	SW	MATE ACREAGE OF NOM	O							
-										
	Acrea	age Justificat	ion:	ω,	The second secon	State Control of the				
:			The second secon							
	<u>}</u>					*				
					•					
	Ţ				- sae					
•	1					B				
:										
			/							
	ļ ·									
						,				
Ċ	•									
	<u> </u>									
11	FORM	PREPARED BY								
			s, Sr. Park H	is	torian					
,	ORGANIZ	ZATION				OATE				
	ì	ICPPC				28 Feb. 75				
		ANO NUMBER: 17 Georgia Ave	ກາງຄ							
	CITY OR			Is	TATE					
	Sil	ver Spring		-	Maryland					
12										
_	State Liaison Officer Review: (Office Use Only)									
	Significance of this property is:									
	National State Local									
	}									
			· ·							
	S	Signature			 					
	<u> </u>					The second secon				

4.

This si a typical lock keeper's house of the Chesapeake and Ohio Canal Company. It is 12 stories in height, 3 bays wide and one deep. It has a rather steeply pitched A-roof. There is a stone chimney enclosed within each end wall of the house. There is a central panelled door with an overlight.

There are no windows on the ends except at the gable levels.

The structure is built of rough fieldstone with larger squared stones for corner quoins. The door has an heavy block of cut stone for a lintel. The windows have stone sills and lintels.

There is a heavy protruding box-like wooden cornice along the roof line. The house is built on a hill so the basement becomes a full story at the rear level.

The house appears to be in the process of restoration.



This is a well preserved lock on the Old Chesapeake and Ohio Canal. The heavy timber gates with old iton strap hinges are still in place. The upper one is closed and the canal above the lock is filled with water.

Both the lock and canal itself are is excellent condition at this point. The stonework of the lock is like that of Lock 207, a lock upstream on the canal. There is a spill shute to one side of the lock to change the water level.



NAME OLD HOTEL/STORE?

LOCATION CHO CANAL PENNIFIELD LOCK POTOMAC, MA

FACADE W

PHOTO TAKEN 2/28/75 MOWYER